

Blad1

| IC i lager | Antal per rör | Antal rör | Totalt antal | Pris inkl. moms / st |
|-------------------|-----------------|--------------|--------------|----------------------|
| TTL | | | | |
| PCF7403 | | 1 | 13 | 4 |
| D110 | 25 | 4 | 70 | 3 |
| D160 | | 1 | 23 | 3 |
| TTL / 74LS | | | | |
| 2 | | 1 | 5 | 4 |
| 5 | 25 | 5 | 117 | 2 |
| 13 | 25 | 8 | 179 | 3 |
| 15 | | 1 | 5 | 4 |
| 20 | | 1 | 6 | 6 |
| 30 | 25 | 7 | 156 | 2 |
| 51 | | 1 | 5 | 5 |
| 73 | 25 | 9 | 225 | 3 |
| 75 | 25 | 18 | 450 | 3 |
| 76 | 25 | 5 | 122 | 3 |
| 86 | | 1 | 16 | 30 |
| 90 | | 1 | 4 | 8 |
| 132 | 25 | 10 | 241 | 4 |
| 139 | 25 | 18 | 444 | 4 |
| 151 | 25 | 19 | 444 | 4 |
| 157 | 25 | 9 | 215 | 5 |
| 240 | 18 | 24 | 422 | 5 |
| 241 | 18 | 28 | 491 | 3 |
| 242 | 25 | 22 | 531 | 5 |
| 243 | 25 | 23 | 470 | 3 |
| 245 | 18 | 3 | 54 | 7 |
| 251 | 25 | 21 | 511 | 3 |
| 253 | 25 | 2 | 50 | 4 |
| 257 | 25 | 3 | 75 | 4 |
| 258 | 25 | 2 | 38 | 4 |
| 259 | | 1 | 2 | 10 |
| 261 | | 1 | 6 | 8 |
| 273 | 18 | 10 | 174 | 7 |
| 290 | 25 | 3 | 70 | 6 |
| 295 | | 1 | 6 | 8 |
| 352 | 25 | 3 | 75 | 10 |
| 365 | 25 | 1 | 25 | 6 |
| 366 | 25 | 3 | 75 | 4 |
| 373 | 18 | 2 | 26 | 6 |
| 375 | 25 | 1 | 36 | 6 |
| 377 | 18 | 1 | 18 | 6 |
| 395 | | 1 | 12 | 9 |
| 396 | 25 | 1 | 25 | 8 |
| | | | | |
| CMOS/74HC | Fabrikat | Antal | Pris | |
| 3 | Mitsubishi | 10 | 4 | |
| 8 | Toshiba | 16 | 4 | |
| 42 | RCA | 3 | 7 | |
| 86 | Tohiba | 9 | 7 | |
| 123 | Toshiba | 3 | 7 | |

Blad1

| | | | |
|---------------------|------------------|----|----|
| 160 | RCA | 16 | 7 |
| 157 | Toshiba | 14 | 8 |
| 158 | RCA | 14 | 5 |
| 162 | RCA | 10 | 7 |
| 163 | Philips, PC | 36 | 7 |
| 164 | Toshiba | 13 | 6 |
| 241 | RCA | 18 | 6 |
| 242 | RCA | 6 | 10 |
| 245 | Toshiba | 9 | 10 |
| 365 | RCA | 34 | 6 |
| 574 | Philips | 1 | 8 |
| 4050 | RCA | 22 | 7 |
| 4051 | Toshiba, Philips | 8 | 18 |
| 4060 | RCA | 2 | 20 |
| 4075 | RCA | 9 | 7 |
| 4518 | RCA | 22 | 20 |
| | | | |
| CMOS / 74HCT | | | |
| 0 | Philips | 2 | 7 |
| 73 | PC | 9 | 5 |
| 125 | RCA | 4 | 5 |
| 139 | Elcap | 1 | 7 |
| 162 | RCA | 9 | 7 |
| 241 | RCA | 6 | 7 |
| 242 | RCA | 7 | 7 |
| 251 | RCA | 46 | 4 |
| 258 | PC | 25 | 6 |
| 373 | Toshiba | 10 | 7 |
| 423 | RCA | 67 | 5 |
| 533 | RCA | 16 | 12 |
| 534 | RCA | 28 | 12 |
| 640 | RCA | 31 | 10 |
| 643 | RCA | 27 | 8 |
| 646 | RCA | 10 | 40 |
| 648 | RCA | 7 | 40 |
| 670 | RCA | 15 | 8 |
| 4053 | Philips | 25 | 11 |
| 4060 | Philips | 12 | 11 |
| 4075 | RCA | 35 | 4 |
| 4511 | RCA | 9 | 18 |
| 4514 | RCA | 30 | 30 |
| 4538 | RCA | 6 | 20 |
| | | | |
| CMOS / 4000 | | | |
| 4011 | Toshiba | 8 | 4 |
| 4019 | Toshiba | 23 | 4 |
| 4023 | Philips | 2 | 4 |
| 4026 | RCA | 2 | 15 |
| 4044 | Toshiba | 16 | 4 |
| 4053 | Toshiba | 7 | 7 |
| 4073 | Toshiba | 7 | 4 |
| 4085 | RCA | 17 | 7 |

Blad1

| | | | |
|---|-----------------|----|-----|
| 4097 | RCA | 2 | 50 |
| 14503 B | Motorola | 57 | 10 |
| 4516 | Toshiba | 2 | 10 |
| 4521 | HEF | 79 | 6 |
| 4556 | Toshiba | 7 | 8 |
| 4585 | Toshiba | 9 | 10 |
| Optokopplare | | | |
| 74OL6000 | Optologic | 3 | 10 |
| 74OL6001 | Optologic | 34 | 45 |
| 74OL6010 | Optologic | 40 | 35 |
| 74OL6011 | Optologic | 53 | 35 |
| 4N29 | NEC | 18 | 10 |
| 6N136 | Toshiba | 4 | 10 |
| Mikrodatorkretsar / MC m.fl. | | | |
| 146805 E2P | Motorola | 4 | 50 |
| 68A09 Ep | Motorola | 6 | 100 |
| 6844 P | Motorola | 7 | 70 |
| 68B44 P | Motorola | 6 | 40 |
| 6845 P | Motorola | 2 | 25 |
| 6847 P | Motorola | 6 | 80 |
| 6852 P | F | 1 | 70 |
| 68A52 P | Motorola | 16 | 25 |
| 68B54 P | Motorola | 1 | 35 |
| 6875 L | Motorola | 9 | 50 |
| 68008 P | Motorola | 2 | 50 |
| 68121 L | Motorola | 9 | 150 |
| 68153 L | Motorola | 4 | 100 |
| 68230 P8 | Motorola | 4 | 90 |
| 68230 P10 | Motorola | 4 | 110 |
| 68440 L8 | Motorola | 7 | 700 |
| 68450 P | Motorola | 9 | 300 |
| 68452 P | Motorola | 7 | 50 |
| 68A488 P | Motorola | 6 | 65 |
| 68652 P | Motorola | 6 | 90 |
| 68653 P | Motorola | 2 | 70 |
| 68661 PA | Motorola | 7 | 35 |
| 68661 PB | Motorola | 9 | 35 |
| 68661 PC | Motorola | 9 | 35 |
| 686681 L | Motorola | 6 | 150 |
| P8039 AHL | Intel | 2 | 40 |
| ICL 8212 | Intersil | 4 | 20 |
| 8279-5 | Intel | 4 | 30 |
| WD1770 PH-00 | Western Digital | 3 | 80 |
| WD1772-PH00-02 | Western Digital | 3 | 250 |
| WD1943-PD00-02 | WD | 16 | 250 |
| WD2010 APL | Western Digital | 4 | 55 |
| WD2797 A-PL | WD | 5 | 140 |
| AM7910 PC | Adv. Micro Dev. | 2 | 50 |
| AM7911 PC | Adv. Micro Dev. | 2 | 200 |

Blad1

| | | | |
|-------------------------------------|----------|-----|-----|
| XR14412 VP | XR | 6 | 60 |
| UM6502 | UM | 1 | 200 |
| μPD8226 C | NEC | 6 | 50 |
| Z80-serien | | | |
| Z80A CPU | SGS | 197 | 25 |
| Z80A S10-1 | SGS | 4 | 60 |
| Counters/ Displaydrivers | | | |
| ICM7211 IPL | Maxim | 2 | 70 |
| ICM7212 IPL | Maxim | 6 | 70 |
| ICM7217 BIJI | Intersil | 14 | 100 |
| ICM7224 AIPL | Intersil | 4 | 130 |
| ICM7227 CIPI | Intersil | 8 | 120 |
| A/D, D/A omvandlare | | | |
| ICL7104-19CPL | Intersil | 4 | 400 |
| ICL7129 CPL | Intersil | 5 | 200 |
| ICL7134 UICJI | Intersil | 1 | 250 |
| ICL8052 ACPD | Intersil | 15 | 120 |
| ADC0804 LCN | National | 6 | 100 |
| ICL8068 ACJD | Intersil | 14 | 120 |
| ZN428 E-8 | ZN | 4 | 100 |
| ZN502 | Plessey | 1 | 100 |
| CA3161 E | RCA | 6 | 60 |
| CA3162 E | RCA | 5 | 60 |
| Minnen | | | |
| TMS2732-25JL | Texas | 2 | 40 |
| L6140005 | Intel | 4 | 50 |
| L6160283 | Intel | 3 | 50 |
| Linjära | | | |
| XR320 P | | 5 | 20 |
| XR228 | | 2 | 20 |
| LF356 | National | 3 | 12 |
| LM339 | ST | 6 | 6 |
| LM348 N | NSC | 10 | 5 |
| LM556 | | 4 | 12 |
| NE565 CN | National | 12 | 19 |
| MC1488 | ST | 3 | 20 |
| MC3401 P | Motorola | 14 | 20 |
| MC3420 P | Motorola | 5 | 20 |
| MC3423 P1 | Motorola | 1 | 20 |
| LM3915 | NSC | 3 | 20 |
| TDA7000 | Philips | 2 | 45 |
| ICM7555 IJA | Intersil | 7 | 12 |
| ICM7556 | Intersil | 15 | 18 |
| ULN2801 A | SGS | 5 | 15 |
| ULN2804 A | SGS | 2 | 15 |